

IHT Electrical Safety Guide

OSHA 1910 Subpart S



Step 1

Consult with your OSHA and/or EPLI attorney for counsel in selecting electrical safety training for your organization.



Step 2

After working with your OSHA and/or EPLI attorney, choose **any** electrical training vendor that your legal team agrees will meet all the requirements of OSHA 1910 Subpart S. OSHA 1910 Subpart S is a prerequisite by OEMs for acceptance into IHT training classes.



Step 3

After completing the electrical training, provide the OEM with proper documentation to attend IHT training.

*If your IHT is an electrician and has completed training that meets **ALL** the OSHA 1910 Subpart S requirements, **AND** you can provide the proper documentation, that will satisfy the above requirements.*

